

QUICK TOUR

Portable Tracker FM109



Please carefully read the user guide before use in order to quickly get the right to operate. Product appearance, color and accessories are subject to change without prior notice in this manual!

Functions and Product parameters

- ◆ Waterproof IPX6
- ◆ Real-time tracking
- ◆ Vibration/Displacement/Low battery/Power off alert
- ◆ SOS
- ◆ Magnetic charge
- ◆ AGPS locating

Frequency	WCDMA 900/2100MHz GSM 850/900/1800/1900MHz
Networks	WCDMA/GSM/GPRS
Battery	3.7V 1000mAh
Location time	Cold start 35s-80s
Hot start	1s
Location accuracy	5 meters
Operating temperature	-20°C~+55°C
Dimension	50*50*15mm
Weight	55g
SIM Type	Mini SIM

LED Indicator Definitions

Green Indicator: GSM/GPRS

Status of indicator	Meaning
Flash	GSM/GPRS connected
Continuously in bright status	No GPRS signal
Green Led off	Power off or in sleep mode

Blue Indicator: GPS

Status of indicator	Meaning
Flash	GPS location successful
Continuously in bright status	GPS signal searching
Blue Led off	Power off or in sleep mode

Red Indicator: Power / Charge

Status of indicator	Meaning
Continuously in bright status	Charging
Red Led off	Full Battery or Charged full

Getting Started

Picture 1



Picture 2



Picture 3



Picture 4

- Open the top cover with the screw driver, Insert a mini SIM card support WCDMA or GSM/GPRS network into the slot and make sure the chip side is down.
- Press the orange power button more than 3 seconds, the device would turn on.
- Login to FollowMe tracking portal and add your device. IMEI number can be found under the tracking device.
- Contact us on 7901617 for trouble shooting and further assistance.